
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/30/2009
Test to be performed: Ground Condition: Smoke Dyed Water X Dry ✓ Damp Wet		Supervisor: JAW
Manhole_ID: S01UU_021MH	Test ID: <u>D1032-025017</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S01UU_021MH
0			Water Level	
30.29999924			Dye Test Visible	DYE SEEN AT JOINT
33.40000153			Dye Test Visible	DYE SEEN AT JOINT
36.29999924			Dye Test Visible	DYE SEEN AT JOINT
39.70000076			Dye Test Visible	DYE SEEN AT JOINT
53.70000076			Abandoned Survey	DYE TEST IS COMPLETE